



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Las Cruces

Lease No. 070286

Unit 28

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

October 10, 1956

Well No. 2 Federal located 1980 ft. from [N] line and 660 ft. from [E] line of sec. 33

1/4 of NE 20 30E NMP4
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Dos Hermanos 34dy New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

We started cleaning out and found that the Baker Plug had not been completely drilled out. In drilling this plug we drilled from 1611 to 1614 all of which was pay. We then continued to 1624 now total depth. The following is a sample determination of formation drilled:

1611-1614	100% Limestone	50% For.	50% Oil Stn.
1614-1618	100% "	40% "	40% " "
1618-1621	100% "	80% "	20% " "
1621-1624	100% "	40% "	40% " "

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Hudson & Hudson, Partnership

Address 1316 Electric Building

Port Worth, Texas

By _____

Title Partner