

APPROVED

JUN 12 1952

ACTING DISTRICT ENGINEER

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Law Cross

Lease No. 065873

Unit 14 144

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

June 9, 1952

FEDERAL-CORB

Well No. 1 is located 660 ft. from N line and 660 ft. from W line of sec. 23

38 1/4 23 1-20-6 3-11-6 4-1-6
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
"WILDCAT" 144 New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3512 ft. Est.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

672' total depth of 17 1/2" hole. 656' total depth of 24" hole. Ran 632' of 20" OD 9 5/8 grade 4-40 steel casing with shoe. Set at 632' with 850 sacks of regular cement. Circulated out approximately 425 sacks. Plug down at 2:20 PM June 7, 1952. Released pressure after twelve (12) hours and fifteen (15) minutes. Cement set twenty four (24) hours. Displaced mud with water and tested casing with 600 psi for thirty (30) minutes - no pressure drop. Drilled out cement, shoe and formation to 656' and tested with 600 psi for thirty (30) minutes - no pressure drop. Had 60' of cement inside casing.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company RICHARDSON & SONS

Address Box 1178

WILLIAMS, TEXAS

By [Signature]
J. J. Scarborough
Title Division Office Manager

...the ... of ...
...the ... of ...
...the ... of ...

...the ... of ...
...the ... of ...
...the ... of ...

...the ... of ...
...the ... of ...
...the ... of ...

...the ... of ...
...the ... of ...
...the ... of ...

...the ... of ...
...the ... of ...
...the ... of ...

...the ... of ...

...the ... of ...

...the ... of ...