

APPROVED

JUN 13 1952

C. P. Brown
ACTING DISTRICT ENGINEER

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYLand Office Las CrucesLease No. 065873Unit H-1, 2, 3, 4

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	<u>Drill Stem Test</u>	<u>X</u>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

June 11,

1952

FEDERAL CORP

Well No. 1

is located

660 ft. from(N)
(S)

line and

660 ft. from(E)
(W)line of sec. 2334/4 (1/4 Sec. and Sec. No.)7-20-5 (Range)N. 14. (Meridian)P. M.Willcox (Field)200 (County or Subdivision)New Mexico (State or Territory)The elevation of the derrick floor above sea level is 3519 ft. est.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Test taken June 10, 1952. Total depth 900' - top of packer set at 840'. Tool open one (1) hour - light blow of air. Recovered 140' of drilling mud - no water.

REMARKS: This test taken to determine if the knugler carried water.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company RICHMOND & BASSAddress BOX 1178WILLIAMS, TEXAS

By

J. J. Scarborough
Division Office Manager