

**MAILED COPY**

(SUBMIT IN TRIPLICATE)

**New Mexico**

Land Office


Lease No.

Unit

**Big Sandy**

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

**RECEIVED**



**SUNDRY NOTICES AND REPORTS ON WELLS**

APR 7 1960

NOTICE OF INTENTION TO DRILL	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

**Shell Oil Co. & Texas Crude Oil Co.**

**Big Sandy Unit**

Well No. **2-30** is located **130** ft. from **N** line and **1050** ft. from **E** line of sec. **30**

**34/4, 34/4, Sec. 30**  
(1/4 Sec. and Sec. No.)

**T-20-S**  
(Twp.)

**R-31-S**  
(Range)

**100W**  
(Meridian)

**Undesignated**  
(Field)

**Sandy County**  
(County or Subdivision)

**New Mexico**  
(State or Territory)

The elevation of the derrick floor above sea level is **1568** ft.

**DETAILS OF WORK**

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

We propose to drill the **Shell Oil Co. & Texas Crude Oil Co., Big Sandy Unit 2-30** as a **2200' Taneill Line Test** as follows:

Drill into the redbeds or into the top of the anhydrite to approximately 850' and cement **8-5/8"** casing (circulate cement to surface).

Drill into Taneill Line at approximately 2150' and cement **5 1/2"** casing as provided in Section IV, 3, b, 1, of U.S.G.C. Order R-111-A.

**ILLEGIBLE**

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Texas Crude Oil Company**

Address **1201 V & J Tower Building**

**Midland, Texas**

By

Title **Division Superintendent**

USGS 8, OCC 2, File 1, P 1, Borax Co. 1, Coedon 1, Tri-Service 1, MMS 1, SLS 1.