



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office New Mexico
Lease No. 06818
Under Min. 2142

RECEIVED

JUN 6 1960

SUNDRY NOTICES AND REPORTS ON WELLS E. C.
ARTESIA, OFFICE

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	<u>X</u>
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Shell Oil Co. & Texas Crude Oil Co. June 3, 1960

Well No. 2-30 is located 330 ft. from XXX line and 1650 ft. from XXX line of sec. 30

SW/4, SE/4, Sec. 30 T-20-S R-11-E NE/4
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Undesignated Blair County New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3568 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Run 2142' of 5 1/2", 14#, 3-55 casing set @ 2144' w/25 gr. cement. P. D. 3:00 p.m. (CST)
6-1-60. Run temperature survey. Top of cement @ 1995'. WCC 36 hrs. Bailed hole dry
and drilled plug. Waited 1 hr. No fillup.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Texas Crude Oil Company

Address 1201 V & J Tower Bldg.

Midland, Texas

By Joe L. Howard

Title Division Superintendent

USGS 3, GCS 2, File 1, Pg 1, Bureau Co. 1, Condon 1,

GPO 9 18 507