



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office _____
Lease No. 06610
Unit Big 200
RECEIVED

FEB 4 1960

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

February 2, 1960

Shell-Texas Crude Big 200
Well No. 1-30 is located 330 ft. from N line and 330 ft. from E line of sec. 30
30 (1/4 Sec. and Sec. No.) T-30-N R-31-E 1012
(Twp.) (Range) (Meridian)
Big 200 (Field) Big 200 (County or Subdivision) Big 200 (State or Territory)

The elevation of the derrick floor above sea level is 3573 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

We propose to plug and abandon the lower zone in the subject well as follows:

Fill the 7" casing w/sea water fluid; place a cement plug from 6016-5892' (25 m.); Below Production Packer will be left in hole at 2600'. A cast iron bridging plug will be set at approximately 2600'. The well will be produced only from the Tensill Lias.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Shell Oil Company and Texas Crude Oil Company

Address 1201 V. A. J Tower Building

Midland, Texas

By J. R. Howard
Title Production Superintendent

