

(SUBMIT IN TRIPLICATE)

Land Office New MexicoLease No. NW 0113 487Unit DUNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

October 28, 1963

Box Canyon Unit

Well No. 1 is located 560 ft. from N line and 660 ft. from E line of sec. 12NW NW Sec. 12 28-S 21-E
(Of Sec. and Sec. No.) (Town) (Range) (Meridian)Wildcat (Devonian) Reddy New Mexico
(Field) (County or Subdivision) (State or Territory)The elevation of the derrick floor above sea level is 4678 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate casing jobs, cementing points, and all other important proposed work)

Drilled to 9435', total depth. Plan to plug and abandon as follows:

- Plug # 1, 9341-9229 w/40 sax cement
- " # 2, 8500-8357 w/50 sax cement
- " # 3, 6750-6638 w/40 sax cement
- " # 4, 4800-4688 w/40 sax cement
- " # 5, 3700-3688 w/40 sax cement
- " # 6, 2060-1893 w/60 sax cement
- " # 7, 40-Surface w/60 sax cement

All spaces between plugs will be filled with mud-laden material, in accordance with approved methods.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Marathon Oil CompanyAddress Box 220Hobbs, New Mexico

By _____

Title Asst. Superintendent

(SUBMIT IN TRIPLICATE)

Land Office New MexicoLease No. NM 0143 487Unit DUNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

RECEIVED

SEP 16 1963

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	ARTESIA, OFFICE
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 10, 1963

Box Canyon Unit

Well No. 1 is located 560 ft. from N line and 660 ft. from W line of sec. 12NW NW Sec. 12
($\frac{1}{4}$ Sec. and Sec. No.)22-S
(Twp.)21-E
(Range)

(Meridian)

Wildcat (Devonian)
(Field)Eddy
(County or Subdivision)New Mexico
(State or Territory)The elevation of the derrick floor above sea level is 4678 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Total Depth 2000' Ran 63 jts. 9-5/8" csg. 36#, 8R, J-55, ST&C to 1997'. Setting depth includes Baker diff. fill-up collar 1.65' & Baker guide shoe 1.07'. Cemented 1st stage using 335 sxs. Trinity Lite Water cem. w/12 1/2" gilsonite & 1/4# Flocele per sack w/2% Calcium Chloride followed w/200 sxs. Trinity reg. cem. w/1/4# Flocele per sack 2% gel & 2% calcium chloride. Had good returns while cementing. Opened HOWCO DV tool w/1500 psi & circ. approx. 10 sxs. cement to surf. Circ. hole f/4 hrs. w/approx. 75% returns. Cemented 2nd stage w/475 sxs Trinity Lite Water cement w/12 1/2" Gilsonite per sack & 1/4# Flocele per sack 2% gel & 2% calcium chloride. Had approx. 125 sxs. cement returns to surface. Closed DV tool w/1200 psi. WOC 24 hrs. Press. tested 9-5/8" csg. w/1200# f/30 min., held OK.

DIST:

J. A. Grimes

USGS

D. V. Kitley

L. H. Davis

Commissioner of Public Lands

J. R. Barber File

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Marathon Oil CompanyAddress Box 220Hobbs, New MexicoBy [Signature]Title Asst. Superintendent