



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe,
Lease No. LC 065494
Unit Virgin. loc

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	<input type="checkbox"/>
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	<input type="checkbox"/>
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	<input type="checkbox"/>
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	<input type="checkbox"/>
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	<input type="checkbox"/>
NOTICE OF INTENTION TO ABANDON WELL		<input type="checkbox"/>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Artesia, New MexicoApril 22, 1963Virgin. locWell No. 17 is located 600 ft. from {N} line and 600 ft. from {E} line of sec. 10Sec. 10

(1/4 Sec. and Sec. No.)

20 S.

(Twp.)

41 E.

(Range)

N. 37° 30' E.

(Meridian)

Artesia

(Field)

Sddy

(County or Subdivision)

New Mexico

(State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spudded well on April 20, 1963. On April 23, 1963, ran
405' of 8 5/8" casing and mudded same.

Test on April 24, 1963 showed no water to 1000'.

REPORT

ARTESIA, N.M.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company John A. YatesAddress 523 Harper Building,Alamogordo, New Mexico.

By

Walter CardaTitle Bookkeeper