



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYLand Office Las Cruces  
Lease No. LC 062434  
Unit 7**RECEIVED**  
MAR 1 1963  
R. E. Jane

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Artesia, New Mexico,  
February 1, 19 63Well No. 1 is located 2310 ft. from N line and 2310 ft. from E line of sec. 1SE 1/4 NW 1 Sec. 1 20 South 27 East N.M.P.M.  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)Undesignated Eddy New Mexico.  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is \_\_\_\_\_ ft.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

To confirm oral approval given on 1-28-63, plan to plug and abandon as follows:

knock off 7" pipe at approximately 1434'. Fill hole with heavy mud. Spot 25 sack cement plug from 1800 to 1675'. Spot 40 sack cement plug from 400 to 470'. Pull 8 5/8" casing and set regulation marker in 20 sack cement plug at surface.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company JOHN A. YATESAddress 323 Carper Building,Artesia, New Mexico.By W. A. G. G. G.Title Bookkeeper