

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office _____
Lease No. **LC 059365**
Unit _____



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Big Eddy Unit

January 15, 19**63**

Well No. **2** is located **660** ft. from **N** line and **660** ft. from **E** line of sec. **19**
SE/4, SE/4, Sec. 19 **T-21-S R-28-E** **NMPM**
 (Field) (County or Subdivision) (State or Territory)
Wilcox **Big Eddy** **New Mexico**

The elevation of the derrick floor above sea level is **3198** ft. **RDS**

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On 1-12-63, 9-5/8" OD 32.3#-40#, H=40 & J=55 casing was run and set at 3252' with 1450 sx. Circulated 20 sx. tested casing with 1450 PSI. Ok. Reduced hole to 8-3/4" at 3252 and resumed drilling operations.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Pon American Petroleum Corporation**
 Address **Post Office Box 68**
Hobbs, New Mexico

By _____
 Title **Area Superintendent**