

Form 9-331a  
(Feb. 1961)Budget Bureau No. 42-R358.4.  
Form Approved.

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office .....

Lease No. 16-350797Unit 1

RECEIVED

AUG 5 1963

## SUNDRY NOTICES AND REPORTS ON WELLS

|  |  |
|--|--|
| NOTICE OF INTENTION TO DRILL                   | SUBSEQUENT REPORT OF WATER SHUT-OFF        |
| NOTICE OF INTENTION TO CHANGE PLANS            | SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING |
| NOTICE OF INTENTION TO TEST WATER SHUT-OFF     | SUBSEQUENT REPORT OF ALTERING CASING       |
| NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL | SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR |
| NOTICE OF INTENTION TO SHOOT OR ACIDIZE        | SUBSEQUENT REPORT OF ABANDONMENT           |
| NOTICE OF INTENTION TO PULL OR ALTER CASING    | SUPPLEMENTARY WELL HISTORY                 |
| NOTICE OF INTENTION TO ABANDON WELL            |  |

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

July 24, 1963

Well No. 4111-33 is located 1330 ft. from S line and 1980 ft. from W line of sec. ....
22 (Sec. and Sec. No.) 13 (Twp.) 28 (Range) 11P (Meridian)

Russell (Field) Kddy (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is ..... ft.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

7-24-63 total depth 800 ft. ran 80 1/2 ft 4 1/2" casing, cemented  
4/60 sacks portland, plug down at 1:45 P.M.

RECEIVED  
JUL 30 1963  
U. S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Neil H. MillsAddress Drawer WCarlsbad, New MexicoBy [Signature]Title Agent