

(SUBMIT IN TRIPLICATE)


UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget Bureau No. 42-R358.4.
Form Approved.

Land Office **New Mexico**

Lease No. **NM 0673**

Unit **Walt Canyon Unit**
Eddy County, N.M.



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	
Notice of intention to temporarily abandon well	X

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Walt Canyon Unit

Well No. **1** is located **990** ft. from **{N}** line and **2310** ft. from **{E}** line of sec. **3**

SW SE (1/4 Sec. and Sec. No.) **22-8** **24-E** (Twp.) (Range) (Meridian)
New Mexico (Field) **Eddy** (County or Subdivision) **New Mexico** (State or Territory)

The elevation of the derrick floor above sea level is **3970** ft. **est.**

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

7979' of 4-1/2" casing set at 7992' with 305 sacks Incoor & 4% Gel

Well capped with Christmas tree and shut-in pending evaluation by additional drilling or otherwise of possible zones not tested through perforations from 7932' to 7944'.

Well will be either re-worked or abandoned within approximately 120 days.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Curtis R. Inman**

Address **P. O. Box 737**

Midland, Texas

By **Curtis R. Inman**

Title **Operator**