

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPL
Other instructions on re-
verse side

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

3. LEASE DESIGNATION AND SERIAL NO.
NM 029301

4. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Martha Creek

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Indian Basin (Upper Penn Morrow)

11. SEC. T. R. M. OR BLK. AND
SURVEY OR AREA

Sec 30, T21S, R24E

12. COUNTY OR PARISH 13. STATE

Eddy

NM

14. PERMIT NO.

15. ELEVATIONS (Show whether OF, HT, GR, etc.)

3735' KB 3722' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

*

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

* Isolate tubing leak in long string with permanent tubing plug.

10-21-87 SITP 1700 psig (lower zone), SITP 220 psig (upper zone), SICP 1700 psig (7" csg), SICP 60 psig (9-5/8" csg.). Bled 9-5/8" csg to 0 psig. TIH with CCL and 1.800" O.D. gauge ring. Baker Model K packer at 7269' WLM. Baker locator sub at 9095' WLM. Bottom 5' of prod. tube at 9102' WLM. TOH. TIH and set Baker Model "N" wireline bridge plug at 9101' WLM. TOH. Open 7" casing to atmosphere. Bled to 0 psig in 1/2 hr. 2-3/8" long string followed suite. Install 24 hour chart recorder on upper and lower zone. Witnessed by John Robinson, N.M. Energy & Minerals Dept.

10-22-87 Check press. SITP on lower zone and 7" casing was 0 psig. SITP on upper zone was 220 psig. Mike Williams, N.M. Energy & Minerals Dept., witnessed final pressure. Closed all tree valves, chained and locked tree.

U S ONSHORE OPER

ACCEPTED FOR RECORD

NOV 16 1987

NOV 12 1987

SJS
CARLSBAD, NEW MEXICO

cc: State of New Mexico E&P DIV
Oil Conservation Commission
P. O. Drawer DD
Artesia, NM 88210

RECEIVED
NOV 4 11 00 AM '87
CARLSBAD RESOURCE
AREA HEADQUARTERS

18. I hereby certify that the foregoing is true and correct

SIGNED G. Bunas

TITLE Analyst II

DATE 10-28-87

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____ DATE _____

*See Instructions on Reverse Side