

UNITED STATES DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.
LC-064391-B+NM033049
(CA-EN-272)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐

2. NAME OF OPERATOR
Ralph Lowe

3. ADDRESS OF OPERATOR
PO Box 832, Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface
1980' from North and 1650' from West Lines
of Sec. 29

14. PERMIT NO.
15. ELEVATIONS (Show whether DF, ST, OR, etc.)
3698 GR

7. UNIT AGREEMENT NAME
Indian Hills Unit

8. FARM OR LEASE NAME
Indian Hills Unit

9. WELL NO.
3

10. FIELD AND POOL, OR WILDCAT
Indian Basin, Supper Penn

11. SEC., T., R., M., OR BLM. AND SURVEY OR AREA
29-21-S-24-E

12. COUNTY OR PARISH
Eddy

13. STATE
New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐ PULL OR ALTER CASING ☐
FRACTURE TREAT ☐ MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐ ABANDON* ☐
REPAIR WELL ☐ CHANGE PLANS ☐
(Other) ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☒
FRACTURE TREATMENT ☐
SHOOTING OR ACIDIZING ☐
(Other) ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Ran 7" 23# Casing on Sept. 16, 1965. Set at 7543'. Cemented with 100 Sack 4% Jel, 12# Gilmite, 1/4# Flocl; 180 Sack 4% Jel 1/4# Flocl; 100 Sack Reg. Neat w/ 1/4# Flocl. Temp. Survey Shows top Cement at 6115'. After 48 hours pipe tested with 1500 psi for 30 min. Pipe tested O.K.

RECEIVED

OCT 2 1965

RECEIVED
OCT 2 1965
GEOLOGICAL SURVEY
ALBUQUERQUE, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED Ralph Lowe

TITLE Agent

(This space for Federal or State office use)

APPROVED BY

TITLE

APPROVED

OCT 2 1965

RUDOLPH C. BAIER, JR.
ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side