

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

WELL COMS. COMMISSION

Artesia, NM 88210

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

5. Lease Designation and Serial No.

NM 78215

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Hickory ALV Federal #1

9. API Well No.

30-015-10566

10. Field and Pool, or Exploratory Area

Undesignated Canyon

11. County or Parish, State

Eddy, NM

SUBMIT IN TRIPLICATE

RECEIVED

FEB 24 1993

O.C.D.

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other RECOMPLETION

2. Name of Operator

YATES PETROLEUM CORPORATION

(505) 748-1471

3. Address and Telephone No.

105 South 4th St., Artesia, NM 88210

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Unit F, 1650' FNL, 1650' FWL, Sec. 17-T22S-R24E

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒
- Notice of Intent
-
- ☐
- Subsequent Report
-
- ☐
- Final Abandonment Notice

TYPE OF ACTION

- ☐
- Abandonment
-
- ☐
- Recompletion
-
- ☐
- Plugging Back
-
- ☐
- Casing Repair
-
- ☐
- Altering Casing
-
- ☐
- Other
-
- ☐
- Change of Plans
-
- ☐
- New Construction
-
- ☐
- Non-Routine Fracturing
-
- ☐
- Water Shut-Off
-
- ☐
- Conversion to Injection
-
- ☐
- Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Propose to temporarily abandon Morrow perforations 9886-9898' as follows:
Set SV in packer, get off on/off tool, set RBP at 9800' and test to 2000 psi for 15 minutes.
Spot 250 gals. NeFe 20% HCL acid. TOOH. Perforate the Canyon as follows:
8139, 8140, 8141, 8142, 8143, 8144' (12 holes-2 SPF); 8152, 8153, 8154' (6 holes-2 SPF).
Swab test well. Acidize perms 8139-8154' w/2000 gals 20% NEFE HCL acid.
Swab test. If well is commercial in Canyon, will file recompletion.

14. I hereby certify that the foregoing is true and correct

Signed Shannon J. ShawTitle Production SupervisorDate 2-18-93

(This space for Federal or State office use)

Approved by Shannon J. ShawTitle DEPT. ENGINEERDate 2/19/93

Conditions of approval, if any: