

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Other instruction
verse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐		5. LEASE DESIGNATION AND SERIAL NO. LC 064391-B	
2. NAME OF OPERATOR Ralph Lowe		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR PO Box 832, Midland, Texas, 79701		7. UNIT AGREEMENT NAME Indian Hills Unit	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 660' fr. South Line and 1750' from East Line of Sec. 20		8. FARM OR LEASE NAME Indian Hills Unit	
14. PERMIT NO.		9. WELL NO. 2	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3725 DF		10. FIELD AND POOL, OR WILDCAT Indian Basin (Upper Penn)	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 20-21-S-24-E	
		12. COUNTY OR PARISH Eddy	
		13. STATE New Mexico	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☒	REPAIRING WELL ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐	FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐	SHOOTING OR ACIDIZING ☐	ABANDONMENTS ☐
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) Tubing	
(Other) ☐		(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

ON June 17 Ran 5 1/2" casing set at 7372'. Cemented with 855 Sux Intimty Lute-Wate with 12 1/2# Gilsomite per sack, and 150 Sux Reg. meet. after 36 hours pipe tested with 1500# Pressure for 30 min. pipe tested OK. ON June 22 ran 2 3/8" 4.60# tubing set at 7374'. Well to be completed in the (Upper Penn.)

RECEIVED

JUL 1 1965

O. C. C.
ARTESIA, OFFICE

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

agent

(This space for Federal or State office use)

APPROVED BY
CONDITION

APPROVED

JUN 30 1965
Rudolph C. Baier, Jr.
ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side

RECEIVED
JUN 28 1965
U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO