

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE
(Other instructions
reverse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 07260

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐	7. UNIT AGREEMENT NAME Indian Hills Unit
2. NAME OF OPERATOR Ralph Lowe	8. FARM OR LEASE NAME Indian Hills Unit
3. ADDRESS OF OPERATOR PO Box 832, Midland, Texas, 79701	9. WELL NO. 5
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1470' from West Line and 1230' from South Line of Sec. 33	10. FIELD AND POOL, OR WILDCAT Indian Basin (Upper Penn)
14. PERMIT NO. NSL-367	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 33-21-S-24-E
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4091 GR	12. COUNTY OR PARISH Eddy
	13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) Spud Date

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Well Spudded at 5:00 AM Feb. 3, 1966, ON February 6, 1966
run 13 3/8" 48# J+L Casing. Set at 308'. Cemented with
250 Sack 4% Jel, 1/4# Flocc, + 100 Sack Neat. Top of Cement at
153'. Thru 1" pipe Cemented to surface with 175 Sack regular
Cement. After 24 hours pipe tested with 1000#. Pipe tested
O.K.

Note: No water encountered.

RECEIVED

FEB 15 1966

U. S. G.
ARTESIA, NEW MEXICORECEIVED
FEB 14 1966
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

C. W. MURRAY

TITLE

Agent

DATE

2/11/66


(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE



*See Instructions on Reverse Side