

Form 9-331
(May 1963)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 1189-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ *Drilling*

2. NAME OF OPERATOR
San American Petroleum Corp.

3. ADDRESS OF OPERATOR
Box 68 Hobbs New Mexico

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface
1980' FNL x 660' FEL, Sec. 19 (Unit H, SE 1/4 NE 1/4)

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

7. UNIT AGREEMENT NAME
Big Eddy Unit

8. FARM OR LEASE NAME

9. WELL NO.
9

10. FIELD AND POOL, OR WILDCAT
UNDESIGNATED

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
19-20-31 NM PM

12. COUNTY OR PARISH
EDDY

13. STATE
N. M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
(Other) ☐

PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
ABANDON* ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐
FRACTURE TREATMENT ☐
SHOOTING OR ACIDIZING ☐
(Other) ☐

REPAIRING WELL ☐
ALTERING CASING ☐
ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

On 4-5-65, 11 3/4" OD 42-47# J-55 casing was set at 2257' w/ 850 sq Incon 4% gel, w/ 1/4" flow seal in first 250 sq. + 150 sq. Incon neat. All cement salt saturated w/ 1% cal. cl. cement circulated after M.O.C. 18 hours tested casing w/ 1200 psi for 30 minutes. Test O.K.

Reduced hole to 10 5/8" at 2257 and resumed drilling operations.

RECEIVED

RECEIVED

APR 8 1966

U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Area Supt

DATE

4-7-66

(This space for Federal or State office use)


APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

0-4-USGS-A
1-JWB
1-RV
1-SUSP
1-DERRY R. BASS
1-STATE LAND



*See Instructions on Reverse Side