Form 9-331

Item No. 17 Sampleted Operations

Sinclair Oil & Gas Company P. C. Box 1920, Hobbs, New Mexico Hackberry Hills Unit Well No. 4 Sec. 22-T22S-R2óE., Eddy Co., New Mexico

7-18-66 Acidized Caryon perfs. 10061-91' w/2500 gals. EDA using 36 ball sealers. Max. Press. 5800#, Min. Press. 4400# @ rate of 4.4 BPM Inst. SIP 1000#, 5" SIP 500#. Flow 45 ELW (Brine) plus 60 bbls. AW in 1½ hours. Flow to pits 2½ hrs. to clean up. Flow 2 hrs. 17/64" choke 5200 MCF and 10 BPH Dist. Gvty 60. tubing press. 3250#. Last 5 hrs. flow @ rate 1st 20/64" choke gas rate 5500 MCF dist. 11 bbls. tbg press. 2700#. 2nd hour 20/64" choke rate 5300 MCF dist. 11 bbls. dist. tbg press. 2750#, 3rd hour 20/64" choke rate 5400 MCF, 11 bbls. dist. tbg press. 2570#, 4th hr. 20/64" choke rate 5000 MCF, 11 bbls. dist. tbg press. 2600#.

7-19-66 16 hr. SITP 3967#. On 4 point test flow Caryon perfs. 10061-91' as follows: Rate Time Tbg Press. MCFPD Water Choke Dist. #1 1 Hr. 10/64 3395 2092 5.2 bbls. 1.2 #2 1 Hr. 13/64 3057 3032 4.6 bbls. 1.0 *#3 lHr. 17/64 2230 3544 7.5 bbls. 1.5 2976 5244 #4 1 Hr. 18/64 9.2 bbls. 1.5 * Unstable rate - fluid logged, unloaded w start of last rate. Dist. Gvty. 57.4°. Gas Gvty. .64. Calculated absolute open flow 13,574 MCFPD. Date of test 7-19-66.

Water produced during 4-point test was load water, determined by water analysis test.