

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN THE MANNER
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	7. UNIT AGREEMENT NAME North Cedar Hills Unit
2. NAME OF OPERATOR Humble Oil & Refining Company	8. FARM OR LEASE NAME same
3. ADDRESS OF OPERATOR Box 1600, Midland, Texas 79701	9. WELL NO. 1
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 3060 FNL, 1993 FEL, 8 Sec. 5, T-21-S, R-27-E, Eddy County, New Mexico.	10. FIELD AND POOL, OR WILDCAT Wildcat
14. PERMIT NO. —	15. ELEVATIONS (Show whether DF, RT, GR, etc.) later
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 5, T-21-S, R-27-E
	12. COUNTY OR PARISH Eddy
	13. STATE New Mex.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
(Other) ☐

PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
ABANDON* ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☒
FRACTURE TREATMENT ☐
SHOOTING OR ACIDIZING ☐
(Other) ☐

REPAIRING WELL ☐
ALTERING CASING ☐
ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Ran 2527' (77 jts) 8 5/8" casing set at 2548'. Cemented with 575 sgs
Incon neat with 4% Gel and 1/4# Florel per sf followed by 200 sgs
Incon neat with 1/4# Florel per sf. Cement did not circulate. POB
10:30 PM 5-27-66. Top of cement at 250 by temp. survey. WOC
36 hours. Tested casing with 1000# pressure for 30 minutes -
no drop in pressure. Drilling.

RECEIVED

JUN 15 1966

O. C. C.
ARTESIA, OFFICE

RECEIVED
JUN 15 1966
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED A. L. Clemmer TITLE agent

DATE 6-9-66

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL

JUN 1 1966
RUDOLPH C. BAIER, JR.
ACTING DISTRICT ENGINEER

TITLE
WITNESSED BY BAIER

*See Instructions on Reverse Side