

Memo

From
LELAND MERMIS

To 6-2-77

✓ Corinne Grace Jolly Bill #1 SWP

36-22-26

Back side is open. No packs or tubing leaks. Small water leak at air bleed off valve.

Weeds, junk and a show of old pieces around tank area that show where salt water had been dumped.