

STATE OF NEW MEXICO
OIL AND MINERALS DEPARTMENT

DATE RECEIVED		
DISTRIBUTION		
DATE		
FILE		
C.E.O.S.		
LAND OFFICE		
OPERATION		

OIL CONSERVATION DIVISION
P. O. BOX 2089
SANTA FE, NEW MEXICO 87501

SEP 17 '87

O. C. D.

ARTESIA, OFFICE

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR RE-DRILL A DIFFERENT RESERVOIR.
USE THIS LOCATION FOR PERMIT AND FORMS FOR OTHER OPERATIONS.

OIL WELL ☐ GAS WELL ☐ OTHER: Salt Water Disposal Well

Name of Operator

Unichem International, Inc.

Name of Operator

P. O. Box 1659 Eunice, New Mexico 88231

Location of Well

UNIT LETTER I 1650 FEET FROM THE South LINE AND 754 FEET FROM

LINE East LINE SECTION 27 TOWNSHIP 20S RANGE 26E

15. Elevation (Show whether DT, RT, GR, etc.)

3221' GL

State <input type="checkbox"/>	County <input type="checkbox"/>
1. Unit Approval Name	
Springs Unit	
2. Name of Lease Block	
3. Well No.	
# 2	
10. Field and name of Volume	
Bone Springs Farm.	
12. County	
Eddy	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

REPAIRS/REMEDIAL WORK ☐

PLUG AND ABANDON ☐

REMEDIAL WORK ☐

ALTERING CASING ☐

TEMPORARILY ABANDON ☐

COMMENCE DRILLING OPS. ☐

PLUG AND ABANDONMENT ☐

WORK ON ALTER CASING ☐

CHANGE PLANS ☐

CASING TEST AND CEMENT JOB ☐

OTHER Pull tubing and packer and re-place packer & 16 joints of tubing. ☐

Give Date Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6-10-87 Moved onto location, rigged up, pulled 77 joints of tubing, but no packer. Ran impression head back into hole and out.

6-11-87 Took old well head off, put new well head on. went in hole with grapple and shoe. Picked up 6 drill collars & 70 joints of tubing. Went into hole and ran mill for approximately 2 hours. Came out of hole, ran impression block then shut down.

6-12-87 Went in hole with fishing tool, short catch with 2 3/8" scraffle on it. Latched onto top section of packer, came out. Ran center spear in hole trying to catch rest of packer. Could not, came out of hole, shut down.

6-13-87 Ran in hole with tapered grapple, screwed into top of packer and came out of hole with packer. Packed well-head off, shut down. (Packer AD-Baker)

6-15-87 Picked up 6 joints of wash pipe, and drill collars. Ran in hole with tubing, tagged at 2505 feet, washed to 2853 with bottom of shoe. Pulled out leaving drill collars and pipe in hole. Shut down.

continued.....

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Signed Ed Hesselshewndt

TITLE Mgr.

DATE 9-14-87

APPROVED BY Mike Wilson

TITLE OIL AND GAS INSPECTOR

DATE SEP 18 1987

CONDITIONS OF APPROVAL, IF ANY: