

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

OCT 29 '82

O. C. D. 1
ARTESIA, OFFICE

5a. Indicate Type of Lease		
State <input type="checkbox"/>	Fed <input type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.		
NW 05607		

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator Marathon Oil Company /		8. Farm or Lease Name N. Indian Basin Unit Gas
3. Address of Operator P.O. Box 1324, Artesia, New Mexico		9. Well No. Comm "A" 6
4. Location of Well UNIT LETTER J, 1650 FEET FROM THE South LINE AND 1650 FEET FROM THE East LINE, SECTION 4 TOWNSHIP 21-S RANGE 23-E NMPM.		10. Field and Pool, or Wildcat Indian Basin Up. Penn
15. Elevation (Show whether DF, RT, GR, etc.) GR 3846'		12. County Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> See Below

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Pipe surface and intermediate casing valves to surface. Use 1" pipe and valve to be above grade. Main valve to be left open. Fill in collar with sand for personnel safety. Celler boards keep getting stolen. Work to start approximately October 15, 1982.

Inspected by Mike Williams on 10/18/82

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED W. J. Dreyling TITLE Plant Supt. DATE Oct. 29, 1982
APPROVED BY Mike Williams TITLE OIL AND GAS INSPECTOR DATE OCT 29 1982
CONDITIONS OF APPROVAL, IF ANY: