

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN THE
(Other Instru
verse side)

LOCATE*

s on re-

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-0301983

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Yates Pet. Corp.

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Scanlon Delaware

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA31-20-29 Unit B
NMPM

12. COUNTY OR PARISH

Eddy

13. STATE

N.Mex.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☒ GAS WELL ☐ OTHER

2. NAME OF OPERATOR

Harvey E. Yates

3. ADDRESS OF OPERATOR

207 So. 4th Street - Yates Bldg. - Artesia, N. Mex.

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*

See also space 17 below.)
At surface

2310' FEL & 330' FNL of Sec. 31-20S-29E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, OR, etc.)

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

10-6-7-67 - This well was plugged and abandoned by setting plugs as follows:

150' Plug 3300-3150' 60 sx.

100' Plug 1010-910' 35 sx. Tagged cement and found top at 1300'. Pumped in another 35 sx, tagged at 1300'. Filled hole to 1000' with 5 yds of gravel.

100' 996-896' 35 sx.

100' 700-600 35 sx.

20' Plug at surface with regulation marker.

Heavy mud was used between each plug.

USGS will be notified when location is cleaned and ready for inspection.

RECEIVED

NOV 1 1968

RECEIVED
OCT 12 1967
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct.

SIGNED

M. L. Armstrong

TITLE

ARTESIA, OFFICE Agent

DATE

10-11-67

(This space for Federal or State office use)

TITLE

DATE

APPROVED

CONDITIONS OF APPROVAL, IF ANY:

R. L. BELMONT
ACTING DIRECTOR

*See Instructions on Reverse Side