

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-0251

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. ☐ OIL WELL ☐ GAS WELL ☐ OTHER **DRILLING**

2. NAME OF OPERATOR
PAN AMERICAN PETROLEUM CORPORATION

3. ADDRESS OF OPERATOR
BOX 68, HOBBS, N. M. 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

1650' FSL x 660' FEL Sec. 7 (UNIT I, NE 1/4 SE 1/4)

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

7. UNIT AGREEMENT NAME

BIG EDDY UNIT Federal

8. FARM OR LEASE NAME

9. WELL NO.

11
WILDCAT *2nd Sec. West*
Risk-Straw

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

7-20-31 NMPM

12. COUNTY OR PARISH

EDDY

13. STATE

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☒

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☒

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

*Big West Drilling Co. spudded 20" hole 11:PM, 10-13-67.
On 10-15-67, 16" OD 65-75" H-40 + J-55 casing was set
@ 752' w/ 600 psi. 4% Gel + 200 psi. neat + 2% CACL.
Cement circulated. After HOC 24 hours, tested
casing w/ 600 psi for 30 minutes. Test O.K.
Reduced hole to 13 3/4" @ 752 and resumed operations.*

RECEIVED

OCT 18 1967

U. S. GEOLOGICAL SURVEY
BOSWELL, NEW MEXICO

RECEIVED
OCT 19 1967
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

AREA SUPERINTENDENT

DATE

10-18-67

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DISTRICT ENGINEER

DATE

OCT 20 1967

*0-4- USGS-ROS
1- NSD
1- SOSD
1- STAY
1- STATELAND
1- PERRY BASS*

*See Instructions on Reverse Side