

NEW MEXICO OIL CONSERVATION COMMISSION

DRAWER 10
ARTESIA, NEW MEXICO

FIELD REPORT FOR CEMENTING OF WELLS

Operator <u>David Fushen</u>		Lease <u>Indian Hills Mt</u>		Well # <u>7F</u>	
Location of Well	Unit <u>23 1/4 N</u> <u>2 1/4 W</u>	Section <u>16</u>	Township <u>21</u>	Range <u>24</u>	County <u>Eddy</u>
Drilling Contractor	<u>Warton</u>		Type of Equipment <u>Rotary</u>		

APPROVED CASING PROGRAM

Size of Hole	Size of Casing	Weight Per Foot	New or Used	Depth	Sacks Cement
17 "	13 3/8	45 #		30	Ready mix
12 1/4 " 11	8 7/8	32 #		3200	Circ
7 7/8	4 1/2	11.6		10200	450

Casing Data:

Surface _____ joints of _____ inch _____ # Grade _____
(Approved) (Rejected)

Inspected by _____ date _____

Cementing Program

Size of hole ^{12 1/4 17 1/2} 11 3200 Size of Casing 8 7/8 Sacks cement required _____
Type of Shoe used Guide Float collar used ✓ Btm 3 jts welded Thud Lbs
TD of hole 3200 Set _____ Feet of 8 7/8 Inch 32 # Grade J
New ~~used~~ csq. @ ID with 200 sacks neat cement around shoe C, 2% CaCl₂
+ 1200 sax C additives 7 bags 1, 12 1/2 # Gelsolite, 1/4 # Flocc/sack
Plug down @ 6:55 (AM) (PM) Date 6-27-68

Cement circulated No No. of Sacks _____

Cemented by Hall, Burton Witnessed by STamets

Temp. Survey ran @ 2:00 (AM) (PM) Date 6-27-68 top cement @ 245'

Casing test @ _____ (AM) (PM) Date _____

Method Used _____ Witnessed by _____

Checked for shut off @ _____ (AM) (PM) Date _____

Method used _____ Witnessed by _____

Remarks: Tried to fill hole with water. Pumped in about 60 barrels, did not fill. Ran tbg to 245, pull 1 jt. and ran 75 SX C, 4% CaCl₂, 3 bags hulls. No fill, & no fluid showed on tbg. At 5:00 PM 75 SX as above with same results. To fill hole with ready mix.