

Case No. 25-22-26

Michael P. Grace and Corinne Grace - City of Carlsbad No. 1, Eddy County, New Mexico
6603-1980e 25-22-26

Following is a summary of slope tests taken with the best instruments available on the above well. These tests indicate inclination from vertical.

Angle of Inclination (degrees)	Depth
1/2	275
1/2	358
1/2	446
3-1/4	620
3	818
2-3/4	913
2-3/4	997
2-3/4	1,123
3	1,250
2-3/4	1,375
2-1/2	1,542
2-1/2	1,730
2-3/4	1,946
2-3/4	2,030
2-1/2	2,368
2	2,535
2	2,650
2	2,790
1-1/4	3,054
1-1/4	3,273
1-1/2	3,473
1-1/2	3,684
1/2	3,949
1	4,250
1-1/4	4,335
1-1/4	4,631
1	4,895
1-3/4	5,015
1	5,235
1-1/2	5,666
2	5,916
2	6,168
2-1/4	6,240
2	6,710
1	7,220
1	7,560
3/4	7,775
1/2	8,138
1/2	8,590
1/2	8,780
3/4	9,100
1-1/4	9,660
1-1/4	10,135
1-1/4	10,576
1-1/4	10,905
1-1/4	11,030
1-1/2	11,477
1-1/2	11,641
1-3/4	11,970

RECEIVED

JUN 7 1971

O. C. C.
ARTIFICIAL OFFICE

DELTA DRILLING COMPANY

T. C. Carlton, Drilling Supt.

STATE OF TEXAS

COUNTY OF ECTOR

The foregoing instrument was acknowledged before me this 3rd day of June, 1971, by T. C. CARLTON, known to me to be the person whose name is subscribed hereto, who, after being duly sworn, on oath states that the above is true and correct to the best of his knowledge.

Lincoln Edward Notary Public in and for
Ector County Texas