

| | |
|------------------------|---|
| NO. OF COPIES RECEIVED | 4 |
| DISTRIBUTION | |
| SANTA FE | 1 |
| FILE | 1 |
| U.S.G.S. | |
| LAND OFFICE | |
| OPERATOR | 1 |

NEW MEXICO OIL CONSERVATION COMMISSION

RECEIVED

DEC 20 1974

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS

O. C. C.

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

| | |
|---|--|
| 1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/> | 5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/> |
| 2. Name of Operator Corinne Grace | 5. State Oil & Gas Lease No. K-675 & Fee |
| 3. Address of Operator P. O. Box 1418, Carlsbad, New Mexico 88220 | 7. Unit Agreement Name |
| 4. Location of Well UNIT LETTER <u>0</u> <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>25</u> TOWNSHIP <u>22S</u> RANGE <u>26E</u> NMPM. | 8. Farm or Lease Name City of Carlsbad Com |
| 15. Elevation (Show whether DF, RT, GR, etc.) 3226 DF | 9. Well No. 1 |
| | 10. Field and Pool, or Wildcat South Carlsbad Morrow |
| | 12. County Bidy |

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐

PLUG AND ABANDON ☐

CHANGE PLANS ☐

OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒

COMMENCE DRILLING OPNS. ☐

CASING TEST AND CEMENT JOBS ☐

OTHER ☐

ALTERING CASING ☐

PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

11/29/74 Rig unit up, well having 100 psi on tubing, bled well down. Rigged up to swab. Well having no fluid in hole to 3650'. Closed well in overnight.
11/30/74 Made run with swab to 4650. No fluid in hole, shut well in for new sand line in morning.
12/1/74 Spooled old sand line off rig. Rig up to run new sand line. Tried to make sand line spool right, no good spool sand line off. Shut down overnight.
12/2/74 Putting new sand line on rig and building line up on spool
12/3/74 Finished putting sand line on rig. Poor rope socket. Make up knife, pan knife in hole found plugs at 6212, 9911, 10335, 10590, 10823. Clean from 11420
12/4/74 Ran sand line to 11440. Came out of hole. no fluid in hole. Shut down for night
12/5/74 Made one run with swab down to 11,100 feet no fluid in hole. Wait on orders
12/6/74 Closed well in for B.O.P.'s in morning
12/7/74 Bled well down, break well head down. Make up B.O.P.'s on well head. Shut down to repair blocks on rig.
12/7/74 Bled well down. Worked tubing for 3 1/2 hrs. Finally unset packer. Layed one joint down. Closed well in overnight for elev. in morning.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED

TITLE

DATE

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

SUPERVISOR, DISTRICT II

JAN 7 1975