

Form 9-331
(May 1963)UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRI DATE*
(Other instructions on re-
verse side)

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. UNIT NUMBER
2. NAME OF OPERATOR S. P. Yates	8. FARM OR LEASE NAME Riggs
3. ADDRESS OF OPERATOR 207 South 4th Street - Artesia, New Mexico 88210	9. WELL NO. 4
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface SW/4 NW/4 SW/4 1650' FSL & 330' FWL Sec. 12-20S-26E	10. FARM AND LEASE OF WELL West McMillan S.A. Co.
14. PERMIT NO.	11. FARM AND LEASE OF WELL Sec. 12-20S-26E, N.M.
15. ELEVATIONS (Show whether RF, RT, GR, etc.) 3276' GL	12. COUNTY OF FARM, LEASE, OR WELL Eddy A. Mex.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <u>Spud and set Conductor Pipe X</u>	
(Other) <input type="checkbox"/>		(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zone pertinent to this work.)*

12-5-70 - Spudded at 1:00 PM. - 12-5-70

Ran 1 jt of 12½" conductor pipe and cemented with 3 yards of Ready-Mix.

RECEIVED

RECEIVED

DEC 10 1970

DEC 11 1970

U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICOG. G. O.
ARTESIA, OFFICE

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Engineer

DATE

12-9-70

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL IF ANY

TITLE

DATE

ACCEPTED FOR RECORD PURPOSES
DEC 10 1970
Date
ACTING District Engineer

*See Instructions on Reverse Side