

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN  
(Other inst  
verse side)IPPLICATE\*  
ons on re-Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM - 04557

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. UNIT AGREEMENT NAME Big Eddy Unit
2. NAME OF OPERATOR Champlin Petroleum Company	8. FARM OR LEASE NAME Big Eddy Unit
3. ADDRESS OF OPERATOR P. O. Box 872 Midland, Texas 79701	9. WELL NO. 33
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660' FS & EL, Sec. 4, T-20-S, R-31-E, Eddy County, New Mexico	10. FIELD AND POOL, OR WILDCAT Wildcat
14. PERMIT NO.	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 4, T-20-S, R-31-E
15. ELEVATIONS (Show whether DF, RT, OR, etc.) 3493 DF	12. COUNTY OR PARISH Eddy
	13. STATE New Mexico

16.

## Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON\* ☐CHANGE PLANS ☐

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☒FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐

Spudding

REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT\* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Moran Drilling and Production Co. spudded at 3:00 PM February 3, 1971. Drilled 15" hole to 846' where 11-3/4", 42#, H-40 casing was set at 845' and cemented with 325 sacks class "C" w/2% CACL, 4% gel & 1/2# flocele per sack. Tailed in with 200 sacks neat w/2% CACL and 1/2# flocele per sack. Plug down at 10:15 AM February 5, 1971. WOC 12 hrs. Tested casing and blowout preventers to 600# for 30 min. Tested OK. Reduced hole to 11" @ 846' and resumed drilling operations.

RECEIVED

FEB 11 1971

O. C. C.

ARTESIA, OFFICE

RECEIVED

FEB 10 1971

U.S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct.

SIGNED

*Walter M. Randolph*

TITLE

District Clerk

DATE

February 8, 1971

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

ACCEPTED FOR RECORD PURPOSES

FEB 10 1971

Date

ACTING District Engineer

\*See Instructions on Reverse Side