<u>4-11-74</u> Ran outside cutter on 12 jts of wash pipe. Made cut on fish @ 11,363. Pulled 133 stands & SDON.

<u>4-12-74</u> Finished POOH w/fish. Rec'd 7 jts tbg, 4 subs & blast jts. Total 236.57 ft. Fish remaining IH, consist of 1 cut off jt of tbg, 1-3 ft perf'g sub & on-off tool w/plug, 6' sub & retrieva-D. WBIH w/2-3/8 overshot, stopped 12 stands off btm & SDON

<u>4-13-74</u> Finished GIH, caught fish. Unable to screw seal assembly or release on-off tool. Jarred on fish 45 min & parted on-off tool. POOH w/fish. Rec'd 1 cut off jt of tb 3' perf sub & upper assembly of on-off tool Well started flwg while OOH. Loaded hole w/ 65 bbls 9.2# brine wtr. WBIH w/3-13/16 x 3-1/16 washover shoe, 1 jt of wash pipe, jars, DC's & 42 stands tbg. SDON

<u>4-14-74</u> Finished GIH w/wash pipe. Washed & milled from 11,390-11,401. Circ hole clean rec'd frac sand & steel shavings, pulled 12 stands & SDON. 4-15-74 SD

<u>4-16-74</u> POOH w/wash pipe. Started BIH w/ short catch overshot. Ran 100 stands & SD to repair clutch on Unit

4-17-74 WO Unit, 4 hrs. repairing clutch, FGIH, caught fish. Unscrewed seal assembly. COOH, rec'd on-off tool, 6 ft sub & pkr seal assembly. Prep to run retrieving tools to retrieve pkr.

4-18-74 Well pressured up to 200# after being SI over night. Bled off press & load ed hole w/40 bbls of wtr. Ran Baker packer retrieving tool, bumper sub, jars, 6 DC's & 3 jts tbg. Brake drum on unit cracked, SD for repairs. Will be dwn for one week repairing drum.

RECEIVED

APR 2 2 1974 U.S. GEOLOGICAL SURVEY ARTES A, NEW MEXICO