

9-5/8" @ 2970'
7" @ 11604'

ANPC/COQUINA: YATES STATE #1, Eddy County, New Mexico,
Burton Flat Field. Recompletion to 11300' Morrow SD.
SITP/Completion WT = 194057.1. APT 188-W-08. 300,000.

9-27-88 8-27-88 8-27-88

8-27-88 SITP 2960 psi, SICP 2850 psi.

8-29-88 SITP 2700 psi, SICP 1800 psi.

8-30-88 SITP 2810 psi, SICP 2810 psi.

8-31-88 SITP 2830 psi, SICP 2830 psi.

9-01-88 SITP 2830 psi, SITP 2860 psi.

9-05-88 SITP 2920 psi, SICP 2940 psi

9-06-88 SITP 2925 psi, SICP 2960 psi

9-09-88 SITP 2990 psi, SICP 3000 psi

9-10-88 SITP 2970 psi, SICP 3000 psi

9-11-88 SITP 2970 psi, SICP 3010 psi

9-12-88 SITP 3000 psi, SICP 3020 psi

9-13-88 SITP 3000 psi, SICP 3000 psi

9-14-88 SITP 3000 psi, SICP 3000 psi

9-15-88 SITP 3000 psi, SICP 3000 psi

9-16-88 NO REPORT

9-17-88 SITP 2900 psi, SICP 2975 psi

9-18-88 SITP 2900 psi, SICP 2975 psi

9-19-88 SITP 2990 psi, SICP 2900 psi. Unexplained slight drop in shut-in pressures from 3050⁺ psi; will continue to monitor. Well is awaiting evaluation of potential frac job on this Honor Morrow completion.

9-20-88 SITP 2900 psi, SICP 2975 psi

9-21-88 SITP 2900 psi, SICP 2975 psi

9-22-88 SITP 2900 psi, SICP 2975 psi

9-23-88 SITP 2880 psi, SICP 2810 psi

ILLECIBLE