

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TR
(Other instructi
verse side)DATE
on reForm approved.
Budget Bureau No. 42-R1424.5. LEASE DESIGNATION AND SERIAL NO.
NM 0558014

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Harris-Bell9. WELL NO.
210. FIELD AND POOL, OR WILDCAT
Golden Lane Field11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec 5-21S-29E

12. COUNTY OR PARISH
Eddy13. STATE
New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

Meadco Properties, Ltd.

AUG 3 1973

3. ADDRESS OF OPERATOR

407 West Wall St., Midland, Texas 79701

D. C. C.

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)

At surface

1980' FNL & 1880' FWL Section 5,
T-21-S, R-29-E, Unit F

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3455 Gr.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) Running 8-5/8" casing

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

7/13/73 Drilled 12-1/4" hole to 3883'. Lost circulation at 2073'. Could not regain circulation. Went to dry drilling with clear water. Ran 93 joints 8-5/8" 28# and 24# casing to 3,883'. Cemented with 400 sacks Halliburton Lite with 5# Gilsontite and 1/4# Flocele per sack. Followed by 200 sacks Class "C" with 1/4# Flocele per sack. Plug down 9:00 p.m. 7/13/73. Cement did not circulate.

7/14/73 Cementing with 1" pipe: 50sx 4% calcium chloride @ 1932'
50sx 4% calcium chloride @ 1900'
100 sx 2% calcium chloride @ 1782'
50sx 7% calcium chloride @ 1708'
50sx 4% calcium chloride @ 1520'
70sx Halliburton Lite @ 1418'
200sx Halliburton Lite @ 918'
150sx Halliburton Lite @ 418'

7/15/73 WOC 24 hrs.

7/16/73 Tested BOP to 1500# for 30 min. Tested okay. Started drilling ahead in 7-7/8" hole

18. I hereby certify that the foregoing is true and correct

SIGNED

Dele C. Balm

TITLE

Agent

DATE

7/31/73

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side

