Form 9-331 (May 1963)

SHOOT OR ACIDIZE

REPAIR WELL

STATES SUBMIT IN TRIBLICATE* THE INTERIOR (Other Instructions on re-**UNITED STATES**

CHANGE PLANS

SHOOTING OR ACIDIZING

Casing Job

LEASE DESIGNATION AND SERIAL NO.

DEPART	NF-01/17023-1				
SUNDRY NOT (Do not use this form for propo Use "APPLIC	6. IF INDIAN, ALLOTTEE OR TRIBE NAME				
OIL GAS OTHER		RECEIVED	7. UNIT AGREEMENT N.		
2. NAME OF OPERATOR		•••	8. FARM OR LEASE NA	ME	
Phillips Petroleum Company L. AUG 2 1973			James-C		
3. ADDRESS OF OPERATOR			9. WELL NO.		
Room 711, Phillips Build LOCATION OF WELL (Report location See also space 17 below.) At surface 1980! FS and 660! FW	10. FIELD AND POOL, OR WILDCAT Cabin Lake (Forrow) 11. SEC., T., R., M., OR BLK. AND SURVEY OR ABEA 35, 21-S, 30-E				
14. PERMIT NO.	15. ELEVATIONS (Show whether	15. ELEVATIONS (Show whether DF, RT, GR, etc.)		H 13. STATE	
	3217' DF, 3196	'Gr.	Eddy	New Mexico	
16. Check A	ppropriate Box To Indicate	Nature of Notice, Report, or	Other Data		
		BSEQUENT REPORT OF:			
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING ALTERING		

(Norr: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) (Other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Cactus drilled 15" hole to 3638', conditioned hole. Schlumberger ran caliper, BHC-sonic-GR-logs f/3587' to surface. Conditioned hole. Set 88 joints (3638') 10-3/4" O.D., 51#, K-55 ST&C, A cond. casing at 3638'. Howco cemented w/2650 sx Trinity LW cmt w/2% CaCl2, 21# salt/sx and 1/1# Flocele/sx, followed by 300 sx class C cmt w/2% CaCl2 and 19.6# salt/ sx. Plug to 3599' w/340 BW. Max press 1000#, bumped plug w/1400#. Circ 500 sx cement. Job complete at 2:30 A.M., 7-26-73. WOC 24 hours, tested BOP and csg to 2000# for 1/2 hr, okay. Drilled cement 3560-3599', float at 3599', cmt to 3630'. Tested csg w/1000# for 1/2 hr, okay. Drld cmt 3630-38', tested w/600# for 1/2 hr, okay. Started drlg ahead on 7-28-73 w/9-1/2" bit at 3638'.

> RECEIVED AUG- 11973

ABANDONMENT*

 $\bar{\mathbf{x}}$

		U.S. DECLOSION SUPPLY OF THE PROPERTY OF THE P			
18, I herote county, that the tote	egoing is true and correct	Senior Reservoir	Engineer	DATE	7–30–73
ADPAPTROLLD BY CONDICTIONS OF APPROVA	tate office use) TITLE L, IF ANY:			FATTI	
ACTING DISTRICT ENGINEER		ections on Reverse Side			