N. M. O. C. C. COPY	Cap	y 651=
CMay 1963) U' ED STATES SUBMIT IN TR' ATE. DEPARTMT OF THE INTERIOR (Other instruct a re-	Form approve Budget Burea	u No. 42-R1414.
GEOLOGICAL SURVEY	5. LEASE DESIGNATION NM 0541580	AND SERIAL NG.
SUNDRY NOTICES AND REPORTS ON WELLS	6. IF INDIAN, ALLOTTEE	OR TRIBE . AME
(Do not use this form for proposals to drill or to deeped or plug back to a different reservoir. Use "APPLICATION FOR PERMIT-of for such proposals.)		
1. OL GAS WELL OTHER 2. NAME OF OFFERATOR	7. UNIT AGREEMENT NAM	
Cities Service Oil Company // NOV - 7 1973	8. FABM OR LEASE NAME Government T	E
3. ADDRESS OF OPERATOR	9. WELL NO.	
P. 0: Box 4906 - Midland, Texas 79701 D. C. C. 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements) OFFICE See also space 17 below.)	10. FIELD AND POOL, OR	WILDCAT
At surface 810' FNL & 1980' FWL of Section 14.	Undesignated	Morrow
T-20-S, R-28-E, Eddy County, New Mexico	11. SEC., T., R., M., OR BI SURVEY OR AREA	E. AND
	Sec. 14-T20S-F	
	- · · ·	New Mexico
16. Check Appropriate Box To Indicate Nature of Notice, Report, or Ot		nea-meante
	NT REPORT OF:	
TEST WATER SHUT-OFF PULL OR ALTER CASING WATER SHUT-OFF	REPAIRING WE	
FRACTURE TREAT MULTIPLE COMPLETE FRACTURE TREATMENT SHOOT OR ACIDIZE ABANDON* SHOOTING OR ACIDIZING	ALTERING CAS	
REPAIR WELL CHANGE PLANS (Other)		
(Other) (Norg: Report results of Completion or Recompletion 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, in proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical neutral to this work.)	ion Report and Log form	1.)
T.D. 405' Red Bed & Anhydrite. Prep to drill ahead. Well was s 10-26-73. Drilled to a T.D. of 405' and ran 12 1/4 Jts. (380.65 H-40 casing set and cemented @ 405' w/300 sacks Class C w/2% Car Circulated 25 sacks to pit. Plug down @ 11:45 A.M. on 10/27/73. 15' in 3 hrs. Filled annulus to surface w/Pea gravel. WOC 27 h OD casing to 700 psi for 30 minutes with no drop in pressure.	') 13 3/8" OD Cl ₂ /Sack Cemen	48 <u>-</u> t.
USGS was notified but did not witness.		
i de la companya de l		
	PA	
	RECEIVEL VOV2 1973 OLOGICAL SU	
	OV2 1973 OLOGICAL SURVES R. NEW MEXICO	
ARTE	0100 1975	
in csy	A NEW SIL	- + -
	OLOGICAL SURVES	
		- λ .
8. I hereby certify that the foregoing is true and correct		
TITLE REGION OPERATION Manager	DATE October	- 30, 1973
(This space for Federal or State office use)		
CONTRIPOSE APPROVAL, IF ANY	DATE	
A NOV 6= 1525		
*See Instructions on Reverse Side		