

N. M. O. C. C. COPY
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 0541580

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Government T

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Undes. Russell Morrow

11. SEC., T., R., M., OR BLE. AND SURVEY OR AREA

Sec. 14-T20S-R28E

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

1. OIL WELL GAS WELL OTHER

RECEIVED

2. NAME OF OPERATOR

Cities Service Oil Company ✓

DEC 21 1973

3. ADDRESS OF OPERATOR

Box 4906 - Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface

ARTESIA, OFFICE

810' FNL & 1980' FWL of Sec. 14-T20S-R28E, Eddy Co., New Mex.

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3246' GR.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETE

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON*

SHOOTING OR ACIDIZING

ABANDONMENT*

REPAIR WELL

CHANGE PLANS

(Other) Cementing 5-1/2" csg.

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

T.D. 11,500' Shale. Prep to perforate and complete. Drilled to a T.D. of 11,500' and ran 255 Jts. (8312.95') 5-1/2" OD 20# N-80 8R and 97 Jts. (3111.05') 5-1/2" OD 17# N-80 8R casing set and cemented @ 11,439' w/825 sacks Class H w/3/4% CFR and 5# KCL/sack cement. Plug down @ 4:20 A.M. on 12-16-73. Bumped float w/2350# - Held OK. Ran temp. survey. Top of cement @ 8590'. WOC 48 hrs.

RECEIVED

U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED E. Spaulder

TITLE Region Oper. Mgr.

DATE December 18, 1973

(This space for Federal or State office use)

APPROVED BY J. C. Smith

TITLE DISTRICT ENGINEER

DATE DEC 19 1973

CONDITIONS OF APPROVAL, IF ANY: