		clst
	NM OIL CONS COMMI	SSION
RECEIVED	Drawer DD Artesia, NM 8821	0
Form 3160-5 UNITED S	TATES APTESIA, NM 8021	FORM APPROVED
June 1990)	THE INTERIOR	Budget Bureau No. 1004-0135 Expires: March 31, 1993
Form 3160-5 UNITED S JUNE 1990) JUN 29 11 34 AN 'GUDEPARTMENT OF BUREAU OF LAND	MANAGEMENT	5. Loser Designation and Serval No.
SUNDER NOTICES AND	REPORTS ON WELLS	NM 0428854
Do not use this form for proposals to drill or t	o deepen or reentry to a different reservoir. MIT— for such proposals RECEIVED	6. If Indian. Allones or Tribe Name
SUBMIT IN T	RIPLICATE	7. If Unit or CA. Agreement Designation
		891012391A
1. Type of Well Owl Cas Well Well Other	M 29.'94	8. Well Name and No.
Name of Operator	0. C. D.	Burton Flat Deep Unit #8
General Atlantic Resources Inc.	RTESIA, OFFICE	9. APE Well No.
3 Address and Telephone No.		30-015-20959
410 17th Street, Suite 1400 /	Denver, CO 80202	10. Field and Pool, or Exploratory Area
4 Location of Well (Footage, Sec., T., R., M., or Survey Description)		Burton Flat
1980' FEL, 660' FSL, Section 27-T	20S-R28E	11. County or Parish, State
		Eddy
CHECK APPROPRIATE BOX(s) TO	INDICATE NATURE OF NOTICE, REPOR	RT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	
Notice of latent	Abandoament	Change of Plans
	Recompletion	New Construction
Subsequent Report	Plugging Back	Nos-Routine Fracturing
	Casing Repair	Weser Shut-Off
Final Abendonment Notice	Altering Cooleg	Conversion to Injection
	X com <u>Temporarily Abandon</u>	_ L_I Dispose Water (Nets: Report rando of multiple consistence on Well
		Completion or Recompletion Report and Log form.)
13. Describe Proposed or Completed Operations (Clearly state all perture give subsurface locations and measured and true vertical depth	at details, and give perturent dates, including estimated date of starting	any proposed work. If well is directionally drilled.
•		
The subject well is currently com 9197'- 9204', and has no tubing is		
bond through the Wolfcamp zone.		
1.1 MMCFPD from the Atoka zone.	oliset wert bal usstantscemb bale	attai, but is flowing
Propose to temporarily abandon #8	well until offset #41 well deple	tes in the Atoka zone
and is tested in the Wolfcamp. R		
it is justified to place cement be		
the #8 well.		

Proposed Procedure:

•

Wireline set CIBP at 9150 PSI and pressure test casing per BLM requirements.

14 I hereby certary that the foregoing is the sea correct Signed M. M. Scott M. Webbride Envil	conmental Coordinator Du
(This space for Federal or State office use) (ORIG. SGD.) JOE G. LARA	PETROLEUM ENGINEER Den 7/27/94 to be conducted within 90 days.
Conditions of approval. I any: See attached. Test	to be conducted within 90 days.
or representations as to any matter within its jurnetiction.	nhe to any department or agency of the United States any false. Scittores or frandelent statement

, : (Rev. 5/23/94)

BUREAU OF LAND MANAGEMENT CARLSBAD RESOURCE AREA

Temporary Abandonment of Wells on Federal Lands

4

Conditions of Approval

According to 43 CFR 3162.3-4-c, " No well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer".

Temporary Abandonment (TA) status approval requires a successful casing integrity test as follows:

- 1. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County call (505) 887-6544 ; for wells in Lea County call (505) 393-3612.
- 2. A bridge plug or packer shall be set at a maximum of 50 feet above any open perforations or open hole.
- 3. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
- 4. The production casing shall be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes with a 10% allowable leak-off.

Wells that successfully pass the casing integrity test will be approved for Temporary Abandonment (TA) status for 12 months provided that the operator:

1. Submits a subsequent Sundry Notice requesting TA approval,

2. Attaches a clear copy or the original of the pressure test chart,

3. And attaches a detailed justification why the well should not be plugged and abandoned.

The TA status could be extended without another casing integrity test provided there was no leak-off during the test.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

1. A procedure to repair the casing so that a TA approval can be granted.

2. A procedure to plug and abandon the well.