

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPL.  
(Other instructions on re-  
verse side)Form approved.  
Budget Bureau No. 42-R1424.5. LEASE DESIGNATION AND SERIAL NO.  
NM 0455458

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)1. **RECEIVED**OIL WELL ☒ GAS WELL ☐ OTHER ☐2. NAME OF OPERATOR  
Yates Petroleum Corporation / DEC 21 19733. ADDRESS OF OPERATOR  
207 South 4th Street - Artesia, NM 882104. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)  
At surface 1980' FSL & 660' FWL of Sec. 29-20S-28E

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Federal "DC"

9. WELL NO.

10. FIELD AND POOL, OR WILDCAT

11. SEC., T., R., M., OR BLK. AND

SURVEY OR AREA  
Sec. 29-20S-28E

Unit L NMPM

12. COUNTY OR PARISH 13. STATE

Eddy

NM

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3239' GR

## 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON\* ☐CHANGE PLANS ☐

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☒FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT\* ☒(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

12-19-73 - TD 670'. We have a slight show of gas and a hole full of water. We propose to Temporary Abandon this well for 30 days for possibly deepening.

11-30-73 - Spudded 10" hole at 10:10 AM 11-29-73.

12-9-73 - Ran 9 jts of 8-5/8" 24#, H-40 (285') hung on with clamps at 285'. Reduced hole to 8" and resumed drilling.

**RECEIVED**  
DEC 19 1973  
U. S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Engineer

DATE

12-19-73

(This space for Federal or State office use)

APPROVED BY

TITLE

DISTRICT ENGINEER

DATE

CONDITIONS OF APPROVAL, IF ANY:

**RECEIVED**

U.S. DEPARTMENT OF  
THE ARMY  
WASHINGTON, D.C. 20315