

UNITED STATES M. O. C. & COPY  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 0560293

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Federal 4

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Wildcat

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 4, T-20-S, R-28-E

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Jake L. Hamon

3. ADDRESS OF OPERATOR

908 Vaughn Building, Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)  
At surface

1830' FSL & 1980' FEL of Section 4, T-20-S, R-28-E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3300' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON\*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Drilled cable tool hole to TD of 214' and hole lost fluid at 210'. Hole caved in and cleaned out from 80' back to 216'. Secured permission from USGS to set 9-5/8" at 216'. Ran 6 jts. of 9-5/8", 40#, J55, used casing and set at 216' ground. Cemented with 125 sks of Incor + 2% CaCl. Plug down @ 12:45 P.M. 12-4-73. Job by Halliburton. Cement did not circulate. WOC 3 hours and ran 1" to 75' and cemented with 100 sks of Incor + 2% CaCl. Cement circulated. Job complete @ 5:00 P.M. 12-4-73.

RECEIVED

DEC 18 1973

U. S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Clerk

DATE 12-17-73

(This space for Federal or State office use)

APPROVED BY

TITLE

DISTRICT ENGINEER

DATE

DEC 19 1973

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side