

N. M. O. C. G. COPY
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY
SUBMIT IN TRIPLI
(Other instructions
verse side)Form approved.
Budget Bureau No. 42-R1421.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR Cities Service Oil Company		8. FARM OR LEASE NAME Government U	
3. ADDRESS OF OPERATOR Box 4906 - Midland, Texas 79701		9. WELL NO. 1	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1980' FNL & 1980' FEL, Sec. 22-T20S-R28E, Eddy Co., N. Mex.		10. FIELD AND POOL, OR WILDCAT Undes. Morrow	
14. PERMIT NO.		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 22-T20S-R28E	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3233' GR.		12. COUNTY OR PARISH Eddy	
		13. STATE New Mexico	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other) Cementing 5-1/2" casing

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

T.D. 11,490' Shale. Waiting on completion unit. Drilled to a T.D. of 11,490' and ran 27 Jts. (1139.79') 5-1/2" OD 20# N-80 and 255-1/2" Jts. (10332.21') 5-1/2" OD 17# N-80 casing set and cemented @ 11,490' w/710 sacks Class H with 3/4% CFR-2 and 5# KCL/sack cement. Plug down at 11:10 A.M. on 3-5-74. Bump Float with 2700# - Held O.K. WOC 8 hrs. Ran Temp. Survey. Top of cement @ 9,110'. WOC 72 Hrs. Total WOC Time, 80 Hrs.

RECEIVED

U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Region Oper. Mgr.

DATE March 12, 1974

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

MAR 15 1974

J. L. PEEBLES

*See Instructions on Reverse Side