

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

RECEIVED

Nov 5 9 59 AM '96

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

FORM APPROVED

Budget Bureau No. 1004-0135

Expires: March 31, 1993

5. Lease Designation and Serial No.

NM 0556290

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Gila Federal #2

9. API Well No.

10. Field and Pool, or Exploratory Area

East Burton Delaware

11. County or Parish, State

Eddy County, NM

SUBMIT IN TRIPLICATE

N.M. Oil Cons. Division

811 S. 1st Street

Artesia, NM 88210-2834

NOV 14 1996

1. Type of Well

☐ Oil Well

☐ Gas Well

☒ Other

Dry

2. Name of Operator

J.C. Williamson

3. Address and Telephone No.

P.O. Box 16 Midland TX 79702 (915) 682-1797

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1980' FSL & 1980' FEL
Section 9 T20S R29E

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment Notice

TYPE OF ACTION

☐ Abandonment

☐ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☒ Other Plugged & abandoned

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut-Off

☐ Conversion to Injection

☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Dear Sirs:

The location pad for this well is now covered with a gasoline gathering system. I gave the people who started this gas system permission to use the southwest corner of this pad to put a pumping station house. They went in and put about a foot more of caliche over the whole thing and spread out over the whole pad. We went in and dug out this wellhead and re-entered and plugged as directed, even though we were only 8' from a high pressure gas line and probably only 10' from the fan of an operating compressor and did the work as shown on this approval report. We refilled the cellar, restored the caliche, and turned the location back to the gas company whose name has been changed three times since the report was approved on November 18, 1993.

Thank you.

SEE ATTACHED.

14. I hereby certify that the foregoing is true and correct

Signed

Title

Date

(This space for Federal or State office use)

Approved by (ORIG. SGD.) ALEXIS C. SWOBODA

Title

PETROLEUM ENGINEER

Date

Conditions of approval, if any: