	· .	N.M.O.C.D. COPY	Caper to
form 9-331 May 1963)	UNI <sup>-</sup> ) STATES	SUBMIT IN TRIPLIC (Other instructions of	Form approved.
DEPAF	RTMENT OF THE IN	IERIUR verse side)	5. LEASE DESIGNATION AND SERIAL NO.
	GEOLOGICAL SURVE	EY	N M 0490017-A
SUNDRY N	OTICES AND REPOR	RTS ON WELLS	6. IF INDIAN, ALLOTTEE OR THIBE NAME
(Do not use this form for pr Use "APP	roposals to drill or to deepen or LICATION FOR PERMIT-" for	r plug back to a different reservoir. such proposals.)	
OIL CAS WELL WELL OTHE	:R	RECEIVED	7. UNIT AGREEMENT NAME
Ralph Nix V			8. FARM OR LEASE NAME
ADDRESS OF OPERATOR		MAR 1 3 1980	Fasken Federal
Box 617 Artesi	a. New Mexico 882	IOU.S. GEULUGICAL SURVEY	2
LOCATION OF WELL (Report locati See also space 17 below.)	on clearly and in accordance wi	th anARTESIAguNEN MEXICO	10. FIELD AND POOL, OR WILDCAT
At surface			Avaion
	U.	H-V ALLO SH 1000	11. SEC., T., E., M., OR BLK. AND
1980' FWL & 660' FSL	Sec. 5 T. 21 S. R	• 26 E. LEWIS CH 1800	SURVEY OR AREA
4. PERMIT NO.		and the second	5-21-26
	15. ELEVATIONS (Show whe	ether DF, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE
-	3213 GI	<b>1</b>	Eddy NM
<sup>3.</sup> Check	Appropriate Box To Indic	ate Nature of Notice, Report, or	r Other Data
	NTENTION TO:		EQUENT REPORT OF:
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING WELL
SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING	X ALTERING CASING
REPAIR WELL	CHANGE PLANS	(Other)	ABANDOAMENT
(Other)		(NOTE: Report resu	alts of multiple completion on Well mpletion Report and Log form.)
nent to this work.) *	<sup>rectionally</sup> drilled, give subsurfac I in frac tank and f		tes, including estimated date of starting any tical depths for all markers and zones perti-
March 6, Halib pl fo	ourton Treated well us 240 bbls Geled v prmation too tight.	with 2,000 gallons 7 <sup>1</sup> / <sub>2</sub> ; water. Attempted to Fra . A total of 276 bbls	ac treatment but
ар ар	proximately 150 bb	00#. Well shut in for Is gelled water. Swabbed CF. Flowing pressure 20	d down flowing gas
March 7, Shut	in well head press	sure 2200# at 8:AM ble water. Swabbed 2-3 bbls	ew well for 15 hrs
2 Re	hours went in with	ure 2260# at 8:AM Ble n swab and did not enco it and shut well in for 12.	ounter solid fluid.
March 12 Shut i	n well head pressur	re 2700# waiting for a	connection
. I hereby certify that the foregoin,	is true and correct		
Norta Ki	hale log		7 +0 00
SIGNED	TITLE TITLE	Agent	<u>JATE</u> <u>3-12-80</u>

\*See Instructions on Reverse Side