

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPL
(Other Instructions
verse side)

16-
re-

Form approved
Budget Bureau No. 42 R1424

5. LEASE DESIGNATION AND SERIAL NO.

NM 18293

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Government AA

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Undesignated Morrow

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 23-T20S-R28E

12. COUNTY OR PARISH 13. STATE

Eddy

New Mexico

1. ☐ OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR
Cities Service Oil Company ✓

3. ADDRESS OF OPERATOR
Box 1919 - Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

660' FNL & 1980' FWL of Sec. 23-T20S-R28E, Eddy Co., N. Mexico.

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3227' GR.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other) Cementing 5-1/2" Casing

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

T.D. 11,533' Shale. Drilled to a total depth of 11,533'.
Ran casing as follows:

26 Joints (1137.59') of 5-1/2" OD 20# 8R LT&C N-80 Casing
257-1/2 Joints (10,374.01') of 5-1/2" OD 17# 8R LT&C N-80 Casing

Casing set at 11,533' and cemented with 900 sx Class H with 3/4% CFR2 and 5#
KCL/Sack. Plug down at 9:35 A.M., 9-25-74. Bumped float with 2500# - Held Ok.
Ran temperature survey. Top of cement at 8180'. WOC 8 hours.

RECEIVED

OCT - 2 1974

U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Region Oper. Mgr.

DATE

Sept. 30, 1974

(This space for Federal or State Office use)

APPROVED BY

TITLE

DATE

OCT 4 1974

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side