

LIVINGSTON RIDGE UNIT #1
SECTION 36, T21S, R30E
EDDY COUNTY, NEW MEXICO

RECEIVED

AUG 30 1974

O. C. C.
ARTESIA, OFFICE
12 hours

July 31, 1974	Spudded well at 9 p.m. to a depth of 10'	12 hours
August 1, 1974	Drilled from 10' to 15'	8 hours
August 2, 1974	Drilling 15' to 17' - repair on rig - sand caving	8 hours
August 3, 1974	finished repair on lines - cleaning out	8 hours
August 4, 1974	Drilling 17' to 20' Sand caving bad	8 hours
August 5, 1974	Cleaning out - set joint of pipe for surface	8 hours
August 6, 1974	Drilling 20' to 22' caliche	8 hours
August 7, 1974	Repair on rig clutches	8 hours
August 8, 1974	Drilling 22 to 25' caliche	8 hours
August 9, 1974	Off	
August 10, 1974	Drilling 25 to 27 working on water tank	8 hours
August 11, 1974	Drilling 27 to 29' repair on rig	8 hours
August 12, 1974	Repair on rig	8 hours
August 13, 1974	Finished repair on rig	8 hours
August 14, 1974	Drilling 29 to 32' caliche	
August 15, 1974	Drilling 32 to 35 caliche	
August 16, & August 17, 1974	Drilling 35 to 37' working on rig clutches	16 hrs
August 18, 1974	Off	
August 19, 1974	Drilling 37 to 39' caliche	8 hours
August 20, 1974	Drilling 39 to 42' caliche	8 hours
August 21, 1974	Drilling 42 to 45' caliche	8 hours
August 22, 1974	Drilling 45 to 48' " "	
August 23, 1974	Drilling 48 to 52' " "	
August 24, 1974	Drilling 52 to 55' " "	
August 25, 1974	Drilling 55 to 59' " "	
August 26, 1974	Drilling 59 to 63' " "	
August 27, 1974	Grined Out	