

LIVINGSTON RIDGE UNIT # 1
SECTION 36, T21S, R30E
EDDY COUNTY, NEW MEXICO

RECEIVED

September 21, 1974 Rained out.

September 22, 1974 Rained out.

September 23, 1974 Rained out.

September 24, 1974 Tried to get into location and could not.

September 25, 1974 Repairing motor. (Busted magneto).

September 26, 1974 Repairing motor. (Busted magneto).

September 27, 1974 Rain washed in around surface pipe. Worked 10 hrs.

September 28, 1974 Rain washed in around hole. Hole caved
in around surface casing. Worked 8 hrs.

September 29, 1974 Changed rigs. Rigged up 36 L Worked 12 hrs.

September 30, 1974 Cleaned out. Caving from 95 to 180!
Hole Caving and mixing mud gel.

October 1, 1974 Set Joint of surface in top of well. Mixing mud. Worked 8 hrs.

October 2, 1974 Drilling from 205 to 215 in red sand.
Cleaned out cavings Show of water at 205 ft. " "

October 3, 1974 Drilling from 215 to 230' in red sand. " "
Hole caving bad.

October 4, 1974 Drilling from 230 to 240' in Red sand & clay. " "
Mixing mud.

October 5, 1974 Drilling from 240 to 245' in red sandy shale. Worked 4 hrs.
Rained out at noon.

October 6, 1974 Drilling from 245' to 250' in red sandy shale. Worked 7 hrs.
Hole caving and cleaning out.

October 7, 1974 250- Hole caved in to 220 ft. Cleaning out cavings
and mixing mud. Worked 8 hrs.

October 8, 1974 Drilling from 250' to 255'. Cleaning out cavings. Worked 9 hrs.

October 9, 1974 255- Hole caved in to 220 ft. Worked 8 Hrs.

October 10, 1974 Mixing mud and cleaning out cavings. Worked 8 hrs.

October 11, 1974 Mixing mud and cleaning out cavings. " "