

LIVINGSTON RIDGE UNIT # 1  
SECTION 36, T21S, R30E  
EDDY COUNTY, NEW MEXICO

RECEIVED

NOV 14 1974

O. C. C.  
ARTESIA, OFFICE

October 12, 1974	Drilling from 255' to 260'. Cleaning cavings.	Worked 8 hrs.
October 13, 1974	Off	
October 14, 1974	Couldn't get into location due to rain.	
October 15, 1974	Rain wash sand in hole to 180'.	
October 16, 1974	At 260' Cleaning out hole and mixing mud.	
October 17, 1974	At 260' Cleaning out hole and mixing mud.	
October 18, 1974	Cleaning out cavings and mixing mud and conditioning hole to run pipe.	
October 19, 1974	Cleaning out cavings and mixing mud and conditioning hole to run pipe.	
October 20, 1974	Off	
October 21, 1974	Cleaned out cavings to bottom @ 260'.	
October 22, 1974	Rained out.	
October 23, 1974	Cleaning out cavings and mixing mud.	Worked 8 hrs.
October 24, 1974	Cleaning out cavings and mixing mudd	Worked 8 hrs.
October 25, 1974	Rained out.	
October 26, 1974	Off	
October 27, 1974	Cleaning out cavings from 170' to 230'.	Worked 12 hrs.
October 28, 1974	Burned out water pump on rig motor.	Worked 8 hrs.
October 29, 1974	Waiting on parts for rig motor.	
October 30, 1974	Repair on rig motor. Install water pump	
October 31, 1974	Repairing motor.	
November 1, 1974	At 260' Put water pump on rig motor. Timing motor.	Worked 8 hrs.
November 2, 1974	Off	
November 3, 1974	Cleaning out cavings. From 180' to 240'.	Worked 9 hrs.
November 4, 1974	Mixing mud and cleaning out cavings. Trying to shut off water flo.	Worked 9 hrs.
November 5, 1974	Mixing mud and trying to shut off water flo.	Worked 9 hrs.