

RECEIVED

LIVINGSTON RIDGE UNIT #1
SECTION 36, T21S, R30E
EDDY COUNTY, NEW MEXICO

JAN 6 - 1975

O. C. C.
ARTESIA, NEW MEXICO

December 13, 1974	Reamed tight hole 340' to 390'. Working 16" pipe Run 1 20' joint in hole.
December 14, 1974	Reaming hole below casing. Under reaming, under casing.
December 15, 1974	Reaming. Reamer hung under casing shoe. Bumped reamer loose, working reamer under casing.
December 16, 1974	Reaming hole, 12 noon-12 mid
December 17, 1974	Reaming hole to 18 in.
December 18, 1974	TD 700' Under ream in hole to 390' Casing hung up at 310 ft.
December 19, 1974	TD 700' to 700'. Reaming from 310 to 390.
December 20, 1974	TD 700' to 700'. Reaming from 390 to 390.
December 21, 1974	TD 700' to 700'.
December 22, 1974	TD 700' to 700'.
December 23, 1974	TD 700' to 700'. 390' 18" Hole.
December 24, 1974	TD 700' to 700'. Fishing for Drill Tools.
December 25, 1974	Shut down.
December 26, 1974	TD 700' Reaming hole at 390'.
December 27, 1974	TD 700' to 390' 18" hole.
December 28, 1974	TD 390' to 390' fishing with ball hook and combination socket.
December 29, 1974	Fishing for drill tools.
December 30, 1974	Fishing for drill tools.
December 31, 1974	Fishing for drill tools.
January 1, 1975	Fishing for drill tools. Run wall hook and comb socket.
January 2, 1975	Fishing for drill tools.