

LIVINGSTON RIDGE UNIT # 1  
SECTION 36, T21S, R3CE  
EDDY COUNTY, NEW MEXICO

January 3, 1975	TD 700' to 390' reamed.
January 4, 1975	Fishing for tools.
January 5, 1975	Fishing for reamer.
January 6, 1975	Fishing for reamer.
January 7, 1975	Fishing for reamer. Broke hold on fish.
January 8, 1975	Fishing for reamer.
January 9, 1975	Run Wall Hook.
January 10, 1975	Waiting on slips for fishing tool.
January 11, 1975	Jarring on stuck tools.
January 12, 1975	Mixing Mud.
January 13, 1975	Mixing Mud- 20 sks..
January 14, 1975	Cemented surface pipe at 310'.
January 15, 1975	W. O. C.
January 16, 1975	W O. C. 700' T.D.
January 17, 1975	Drilled cement plug 20' cement in pipe and Cleaned out to 324'.
January 18, 1975	Cleaning out hole below pipe. Drilled from 324' to 425'.
January 19, 1975	from 425' to 440' cleaned out.
January 20, 1975	from 440' to 460' cleaned out.
January 21, 1975	from 460' to 500' cleaned out.
January 22, 1975	from 500' to 530' cleaning out, cuttings.
January 23, 1975	from 530' to 560' cleaning out.
January 24, 1975	from 560' to 600' cleaned out cuttings.
January 25, 1975	Junk in hole waiting on magnet to run for junk.
January 26, 1975	Junk in hole waiting on magnet to run for junk.
January 27, 1975	From 600' to 620' cleaning out cuttings and plungs. Drilling on junk. (8a.m. to 4p.m.)
January 28, 1975	From 620' to 640' cleaning out 18" hole. 11 hrs.

RECEIVED

FEB 6 1975

O. C. C.  
ARTESIA, OFFICE