

---LIVINGSTON RIDGE UNIT # 1
SECTION 36, T21S, R30E
EDDY COUNTY, NEW MEXICO

March 18, 1975	To 1190' Reaming hole to 12". Generator out on drill motor. 12 hrs. Trip to Hobbs shop to repair generator. 12 hrs.
March 19, 1975	To 1190' Reaming 12 hrs. To 1190' Reaming hole to 12". 12 hrs.
March 20, 1975	To 1190' Reaming 12 hrs. 1190' Run 28' joint of 9 5/8 pipe. 12 hrs.
March 21, 1975	1190' Cleaning out hole and cavings trying to work casing in hole. 12 hrs. Cleaned out cavings below casing. 12 hrs.
March 22, 1975	Tools stuck below 1100' Jarring on tools 8 hrs. Pulled tools loose. Hole caved in to 1024'. 12 hrs.
March 23, 1975	Waiting on orders. 24 hrs.
March 24, 1975	Waiting on orders. 24 hrs.
March 25, 1975	T.D. 1090' Waiting on orders. 24 hrs.
March 26, 1975	Waiting on orders. 24 hrs.
March 27, 1975	Waiting on orders. 24 hrs.

RECEIVED

MAR 31 1975

O. C. C.
ARTESIA, OFFICE