

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPL
(Other instructions
verse side)

PE-
10-

Form approved.
Budget Bureau No. 42 R1421
5. LEASE DESIGNATION AND SERIAL NO.
NM 17100

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

RECEIVED

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> DRY	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Yates Petroleum Corporation	8. FARM OR LEASE NAME Federal "DS"
3. ADDRESS OF OPERATOR 207 South 4th Street-Artesia, NM 88210	9. WELL NO. 1
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 330' FWL & 990' FSL of Sec. 29-20S-28E	10. FIELD AND POOL, OR WILDCAT Undesignated
14. PERMIT NO.	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 29-20S-28E Unit M NMPM
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3233' GR	12. COUNTY OR PARISH Eddy
	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	<input type="checkbox"/>	PULL OR ALTER CASING	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	MULTIPLE COMPLETE	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	ABANDON*	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	CHANGE PLANS	<input type="checkbox"/>
(Other)			

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	<input checked="" type="checkbox"/>	REPAIRING WELL	<input type="checkbox"/>
FRACTURE TREATMENT	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
SHOOTING OR ACIDIZING	<input type="checkbox"/>	ABANDONMENT*	<input checked="" type="checkbox"/>
(Other) Spud			

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

8-28-74 - Spudded 10" hole at noon 8-28-74.

TD 285' - Ran 285' of 8-5/8" 24#, J-55 casing set at 285' w/200 sacks of Class C 2% CaCl. Cement circulated. PD 12:00 Noon 10-1-74. WOC 36 hours, bailed hole dry and tested for 1 hour. Tested dry. Drilled plug, reduced hole to 8" and resumed drilling.

RECEIVED
NOV - 7 1974
U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED Eddy L. Hays TITLE Engineer DATE 11-6-74

(This space for Federal or State office use)

APPROVED BY [Signature] TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

NOV 8 - 1974
U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO
ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side